

SCITUATE Fire Department
Activity Tracker Report (Category / Action - Details)
 Activities from 9/29/2018...10/29/2018 | Apparatus Maintenance

	OOS Now	Service \$ Total	Dur Hrs	Date	Persons	Person Hrs
Apparatus Maintenance (16)						
Cohasset E-3 • Repair: Work Order - CLOSED Repair Order: , Urgency: IN-SERVICE, Details: Steering gear box leaking				10/03/18	0	0.00
Actions (1)					0.00	
C30 VIN: 1GNSK3KC9FR305973						
C30 • Repair: Work Order - CLOSED Repair Order: 18-54287, Urgency: LOW IN-SERVICE, Problem: Install UHF radio Mechanic: 10/22/2018 • Installed new Kenwood UHF mobile.				10/18/18	1	0.00
Actions (1)					0.00	
C31 VIN: 1GNEK13Z25J242717						
C31 • Repair: Work Order - CLOSED Repair Order: 18-53704, Urgency: LOW IN-SERVICE, 128919 mi. Problem: Vehicle has no heat Mechanic: 10/4/2018 • Removed and replaced thermostat. Topped off and tested anti freeze to -30F	0.00			10/04/18	1	0.00
C31 • Repair: Work Order - CLOSED Repair Order: 18-53705, Urgency: LOW IN-SERVICE, 128919 mi. Problem: Vehicle Service Mechanic: 10/4/2018 • Inspect brakes to be ok. Installed thermostat.	0.00			10/04/18	1	0.00
Actions (2)					0.00	
C32 VIN: 1FMJU1G50AEB64901						

SCITUATE Fire Department
Activity Tracker Report (Category / Action - Details)
 Activities from 9/29/2018...10/29/2018 | Apparatus Maintenance

<i>Apparatus Maintenance actions, continued...</i>		OOS Now	Service \$ Total	Dur Hrs	Date	Persons	Person Hrs
C32 • Repair: Work Order - CLOSED Repair Order: 18-53939, Urgency: LOW IN-SERVICE, 90290 mi. Problem: Vehicle Service Mechanic: 10/12/2018 • Vehicle Service. Inspect brakes okay Topped off anti freeze. Test- Okay			4.21		10/11/18	1	0.00
C32 • Repair: Work Order - CLOSED Repair Order: 18-53940, Urgency: HIGH IN-SERVICE, 90290 mi. Problem: Front right wheel hanging up Mechanic: 10/12/2018 • Removed wheel. Appears to be bad brake flex hose on passenger side front. Removed line and installed new flex hose. Caliper is new from last brake job. Road tested okay. Torqued wheel to 150 ' lbs			25.08		10/11/18	1	0.00
			29.29			0.00	
<hr/>							
ENG1 VIN: 4ENRAAA8XC1007177							
ENG1 • Repair: Work Order - CLOSED Repair Order: 18-53605, Urgency: LOW IN-SERVICE, Problem: Right rear cabinet door will not latch Mechanic: 10/1/2018 • Removed, cleaned latch and reinstalled.					10/01/18	1	0.00
ENG1 • Repair: Work Order - CLOSED Repair Order: 18-53629, Urgency: HIGH IN-SERVICE, Problem: High beams OOS. Bad turn signal switch Mechanic: 10/2/2018 • Removed and replaced turn signal switch			54.93		10/02/18	1	0.00
ENG1 • Repair: Work Order - CLOSED Repair Order: 18-54288, Urgency: LOW IN-SERVICE, 494501 mi. Problem: Rear tire tread depth getting low Mechanic: 10/23/2018 • Installed goodyear G622 RSD TL H 11R 22.5 (4)					10/22/18	1	0.00
			54.93			0.00	
<hr/>							
ENG2 VIN: 1K9AF4286SN058186							

SCITUATE Fire Department
Activity Tracker Report (Category / Action - Details)
 Activities from 9/29/2018...10/29/2018 | Apparatus Maintenance

<i>Apparatus Maintenance actions, continued...</i>	OOS Now	Service \$ Total	Dur Hrs	Date	Persons	Person Hrs
ENG2 • Repair: Work Order - CLOSED Repair Order: 18-53575, Urgency: IN-SERVICE, Problem: Low oil unable to add prior to going into service for Eng 4				09/30/18	1	0.00

Actions (1)					0.00	
--------------------	--	--	--	--	-------------	--

ENG4 VIN: 4ENRAAA85Y1002606						
ENG4 • Repair: Work Order - CLOSED Repair Order: 18-53574, Urgency: HIGH IN-SERVICE, Details: Wont go into pump gear Problem: Wont go into pump gear. Computer on outside pump panel says module disconnect Mechanic: 10/1/2018 • Screen says no interlock. Ran diagnostic test and found everything to be WNL. Spoke to tech support (Steve -317) and took power from pin 1 and jumped it to pins 2 and 10. Light went out. Appears to be OEM wiring issue. Gov Date 2010. Tested and cannot re-create problem. Vehicle will go back in service and advise crews to test every AM.			16.50	09/30/18	5	82.50

ENG4 • Repair: Work Order - CLOSED Repair Order: 18-53603, Urgency: LOW IN-SERVICE, Problem: Generator Exhaust Mechanic: 10/1/2018 • Repaired exhaust for generator.				10/01/18	1	0.00
---	--	--	--	----------	---	------

Actions (2)					16.50		82.50	
--------------------	--	--	--	--	--------------	--	--------------	--

RES1 VIN: 3C7WRNCL6GG322895						
RES1 • Repair: Work Order - CLOSED Repair Order: 18-53601, Urgency: IN-SERVICE, Problem: Batteries changed out. Vehicle would not start				10/01/18	1	0.00

RES1 • Repair: Work Order - CLOSED Repair Order: 18-53868, Urgency: LOW IN-SERVICE, Problem: Passenger side headlight out		0.00		10/09/18	1	0.00
--	--	------	--	----------	---	------

Actions (2)					0.00		0.00	
--------------------	--	--	--	--	-------------	--	-------------	--

SCITUATE Fire Department
Activity Tracker Report (Category / Action - Details)
 Activities from 9/29/2018...10/29/2018 | Apparatus Maintenance

<i>Apparatus Maintenance actions, continued...</i>	OOS Now	Service \$ Total	Dur Hrs	Date	Persons	Person Hrs
RES1 • Repair: Work Order - REQUEST Repair Order: 18-54063, Urgency: IN-SERVICE, Problem: Service Air Bag Light				10/15/18	1	0.00
Actions (1)						0.00
RES2 VIN: 1FVACWDU6DHFD0057						
RES2 • Repair: Work Order - REQUEST Repair Order: 18-53626, Urgency: IN-SERVICE, Problem: Coolant reservoir leaking				10/02/18	1	0.00
Actions (1)						0.00
Apparatus Maintenance » 16		84.22	16.50			82.50

GrandTotals: **Category Count » 16**
 Duration Hours » 16.50
 Person Hours » 82.50
 (parts & labor) **Service Total \$ » 84.22**